



**SMT. S. R. PATEL
ENGINEERING COLLEGE
DABHI, UNJHA
PIN- 384 170**

**DEPARTMENT OF MECHANICAL
ENGINEERING**

SUBJECT : MATERIAL SCIENCE & METALLURGY

SUBJECT CODE: 131904

INDEX

Sr. No.	Experiment	Page No.	Date	Sign
1	Study of phase diagrams for structure-properties correlation			
2	Study of - iron carbide equilibrium diagram.			
3	Study of optical (metallurgical) microscope.			
4	Preparation of specimen for microscopic examination.			
5	Mounting of Specimen			
6	Microstructural observation of ferrous materials.			
7	Effect of quenching media on hardening of steels.			
8	Determination of hardenability of steels.			
9	Determine the effect of section size on hardness of the			
10	Detection of flaws in materials using ultrasonic flaw			
11	Detection of flaws in materials through dye-penetrates Test			

Study of phase diagrams for structure-properties correlation

Experiment No:-1

Date:

Objective: To study the phase diagram for structure-properties correlation.

Theory:

Phase diagrams are equilibrium diagrams or constitutional diagrams which gives sufficient information concerning the phase changes in many heterogeneous systems such as alloy systems. Phase diagrams are graphical representation showing phase relationship that exists in an alloy as it slowly cools from molten state. These phase diagrams show the limits of composition and temperature within which various constituents and phases of any system are stable. One of the important applications of phase diagram is the study of alloy which exists in different equilibrium composition at different temperature. Knowledge of phase diagram is very helpful in controlling and understanding heat treatment processes. With the help of phase diagram, it is possible to estimate the temperatures at which either melting or phase transformation starts and/or completes.

Some of important characteristics of phase diagram are given below:

1. It is a kind of map or graph that gives the relationship between phases in equilibrium in a system as a function of temperature, pressure, or composition.
2. One can know the melting, solidifying and allotropic change temperature from the diagram.
3. Solubility of alloying element (carbon) at different temperature and in various phases can be known.
4. It gives rough idea about post-solidification structure and properties, with varying carbon content.
5. It is very useful in revealing the path through which changes are likely to take place.
6. It is also helpful for the study of growth and doping of single crystal.
7. It is very useful in heat treatment processes.
8. An equilibrium diagram or phase diagram of an alloy system shows the limits of composition and temperature within which various constituents or phase of an alloy system exist.
9. Through phase diagrams, various purification and separation processes can be understood deeply. For the example the solidification and phase separation of metal alloy can be done effectively through phase diagram studies.

TYPES OF PHASE DIAGRAM:

1. According to number of components present in alloy system:

- i) Single components phase diagrams
- ii) Binary components phase diagrams
- iii) Ternary components phase diagrams


In single components system or phase diagram there is only a single component. A good example of this is the water system where the single components water exists in three phase such as ice, water and water vapor based on the variables or degree of freedom (F) such as temperature and pressure are the variable and composition is not a variable. The phase rule for single components system is given by $F=C-P+2$.

Out of the three variables (T, P and composition) or degree of freedom the phase diagrams of metals are drawn at atmospheric pressure (i.e. pressure changes have negligible effect on solid or liquid metal. Pressure has effect only on gaseous Metal i.e. above boiling point showing variation in composition and temperature only. Hence the phase rule $F= C-P+2$ can be simplified here with the reduced phase rule $F= C-P+ 1$.

2. According to the solubility characteristics of two metals:

ISOMORPHOUS SYSTEM:

An isomorphism system is one in which the two metals are completely soluble in solid as well as in liquid states. It is possible only when two metals have the same type of lattice and similar atomic size. A phase diagram for such a system is shown in fig. the diagram is divided into three different regions a solid phase region at the bottom of the diagram, a liquid plus solid region in the middle and a liquid phase region at the top of the diagram. The line PQR is called a solidus line because the temperature at which the alloys start transformation to liquid phase during heating. Similarly the line PQR is called the liquidus line because at this temperature the alloy becomes completely liquid on heating.



EUTECTIC SYSTEM:

A eutectic phase diagram is obtained when two metals are completely soluble in the liquid state but either partly or completely insoluble in the solid state. Such diagrams show the

existence of a eutectic reactions in which a liquid phase decomposes into different solids. A eutectic reaction can be represented by, *Liquid L* \rightarrow *Solid a* + *Solid B*




Fig.2 : Phase diagram of eutectic system (Cd-Bi)

PERITECTIC SYETEMS:

When the melting points of two metals differ considerable another type of reaction occurs, in which one liquid and one solid combine to form a new solid. Such a reaction is called a peritectic reaction and it is expressed as. *Liquid* + *Solid A* \rightarrow *Solid B*




Fig.3 : Phase diagram of peritectic system (Ag-Pt)

The new solid formed is usually an inter-metallic compound but in some cases it may be a terminal solid solution. The phase diagram showing the occurrence of peritectic reaction is shown in fig. the peritectic reaction occurs at a constant temperature. Some of the typical alloy systems which show the reaction are Fe-C, Ag-Pt, etc.

MONOTECTIC SYSTEM:

In all the types discussed so far, it was assumed that there was complete solubility in the liquid state but it is quite possible that over a certain composition range two liquid solutions formed are not soluble in each other. The two liquids show a miscibility gap over a certain composition range. Such a situation arises in monotectic systems. Where one liquid decomposes into another liquid and one solid. Such a reaction is called a monotectic reaction and can be expressed as follows:

Liquid A \rightarrow Liquid B + Solid

The phase diagram showing the occurrence of a monotectic reaction is shown in fig. some typical alloy systems which show monotectic reaction are Cu-Pb, Cu-Cr, Al-Pb, Zn-Pb.

EUTECTOID SYSTEMS:

In all the previous phase diagrams we have considered liquid to solid or solid to liquid transformation but solid to solid transformations are also common in phase diagrams. One such transformation is called a eutectic reaction in which one solid decomposes into two different solids. A eutectic reaction can be expressed as Solid A \rightarrow Solid B + Solid C

Eutectoid transformation takes place at a constant temperature and the product of the transformation are present as intimate mechanical mixture having a distinct appearance under the microscope the phase diagram showing the occurrence of a eutectoid reaction is shown in the fig. some alloy systems which show eutectoid reaction are Fe-C, Cu-Zn, Al-Mn, Cu-Sn etc.

The important applications of phase diagram can be as follows:

1. To select and control heat treatment process parameter, holding temperature, & the holding time and the various other surface heat treatment process parameters.
2. To produce desired properties in final product to suit the service conditions.
3. To understand the properties of material and contribution towards gaining and insight into the controlled microscopic structure
4. To understand the properties of the materials and the contribution towards gaining and insight into controlled microstructure.
5. To develop a special grade of alloy with optimum combination of properties. Subject to variation in microstructure.
6. One of the important applications of phase diagram is in zone refining of materials to produce ultra clean material (i.e. that is highly level of purity) for various special applications e.g. semi conducting crystals & other high-tech applications.

3. List out the application of phase diagram.

4. Compare solidification characteristics of a pure metal and of an alloy?

5. What is a eutectic reaction? How does it differ from eutectoid reaction?

Date:	Sign:	Grade:
-------	-------	--------

IRON-CARBIDE EQUILIBRIUM PHASE DIAGRAM

Experiment No: 2

Date:

Objective: to study iron-iron carbide equilibrium phase diagram.

Theory:

Like every metal, iron has its definite melting and solidification temperature. Alloying elements influence these temperatures. Iron is an allotropic metal, as depending upon temperature iron can exist in more than one type of lattice structure. The temperature at which the allotropic changes take place in iron is influenced by alloying elements. The most important of which is carbon. This inherent alloying element plays important role in properties of steel and cast iron the fundamental engineering materials.

Different solidification temperatures and temperature of allotropic change with different carbon content are incorporated and plotted in a form of temperature v/s weight percent carbon graph. This graph is known as Iron-Iron Carbide equilibrium diagram. The portion of iron-carbon alloy system that is of interest as shown in **Figure1**. This is the part between pure iron and interstitial compound iron carbide, Fe_3C , containing 6.67 % carbon by weight.




Fig. 1: Fe- Fe₃C phase equilibrium diagram.

This is not true equilibrium diagram as the compound iron carbide will decompose in iron and carbon (graphite). This decomposition will take a very long time at room temperature and even at 700 °C it takes several years to form graphite. Therefore iron-iron carbide diagram,

even though it technically represents metastable conditions, it can be considered as representing equilibrium changes, under conditions of relatively slow heating and cooling.


Significance:

1. It distinguishes steels and cast irons.
2. One can know the melting, solidifying and allotropic change temp. from the diagram.
3. Solubility of alloying element (carbon) at different temperature and in various phases can be known.
4. It gives rough idea about post-solidification structure and properties, with varying carbon content.
5. It is very useful in heat treatment processes.

The diagram shows three horizontal lines, which indicate isothermal reactions. This is observed during solidification.

1) Peritectic reaction:


This is observed at 1498° C. It occurs in 0.18 % carbon steel. The reaction is as follows:



Where, δ = delta iron (ferrite), L = Liquid steel (molten) and γ = Gamma iron (austenite). The steels having carbon less than 0.18% may be termed as hypoperitectic steels while those containing more than 0.18% are termed as hyperperitectic steels. All steels containing carbon in the range of 0.10 to 0.55 % show paratatic reaction. However, commercial heat treatment is not done in delta region.

2) Eutectic reaction:


It is observed only in cast iron containing 4.3 % carbon at 1147° C during cooling. The reaction is as follows:



Cast iron contains carbon in the range of 2 to 6.67 %. Cast irons having carbon less than 4.3% are called hypoeutectic cast irons, while those containing more than 4.3% are hypereutectic cast irons. At 4.3% carbon, when eutectic reaction undergoes the liquid gets transformed into austenite and cementite. This transformed matrix is known as ledeburite.

3) Eutectoid reaction:

This reaction is observed at 723° C. It occurs in 0.8 % carbon steel. The steels containing carbon in the range of 0.008 to 2 % show eutectoid reaction. The steels having carbon less than 0.8% are called as hypoeutectoid steels while the steels having more than 0.8 but less than 2% carbon are called hypereutectoid steels. The reaction is as follows.



This means austenite gets transformed into ferrite and cementite. This mixture is known as pearlite.

This diagram shows the following existing phases which can be explained as follows:

(A) Ferrite: In iron-iron carbide system, ferrite exists in two forms as delta and alpha ferrite. Delta ferrite (BCC) is defined as an interstitial solid solution of carbon in delta region. Alpha iron exists at room temp, which is interstitial solid solution of carbon in alpha region. The solubility of carbon in alpha iron is maximum 0.025% at 723°C and 0.008% only at room temp. Under the microscope, ferrite is seen as homogeneous polyhedral grains.

It is soft and ductile phase. It can not be heat treated. However, it can be hardened by cold working. It is magnetic upto 768° C and then it becomes non-magnetic. Average mechanical properties are: Tensile strength = 276 MPa. Elongation = 40 % in 50.8 mm. Hardness is less than HRB 10 or HRC zero.

(B) Austenite: It is an interstitial solid solution of carbon in γ (gamma) iron (FCC). It is very weak in magnetic property. The maximum solubility of carbon in austenite is 2% at 1147 °C. This phase is stable only upto 723 °C. During cooling, below 723 °C, it decomposes to ferrite and cementite. It is ductile and soft phase. Usually steels are hot worked in austenite region. The grain size of steel at room temp is determined by austenite grain size. Austenite transforms to various phases as pearlite, bainite and martensite. These newly formed phases show properties, which are not present in austenite. e.g. martensite is harder than austenite.

Austenite phase is observed at room temp only in special alloy steels such as austenite stainless steels. For almost all heat treatments, the steels are initially heated in austenite region. Average mechanical Properties are: T.S. = 1034 MPa, Elongation = 10 % in 50.8 mm, Hardness = HRC 40 approx. Toughness is high.

(C) Pearlite: It is the eutectoid mixture containing 0.8% carbon and is formed at 723°C on very slow cooling. It is a very fine platelike or lamellar mixture of ferrite and cementite. The white ferrite background or matrix which makes up most of the eutectoid mixture contains the plates of cementite. 100% pearlite is observed in 0.8% carbon steels. It shows better strength and hardness. Average mechanical properties are: Tensile strength = 828 MPa, Elongation = 20 % in 50.8 mm. Hardness = HRC 20 approx. or BHN 250 to 300.

(D) Cementite: It is an intermetallic compound of iron and carbon. It has a fixed chemical formula, as Fe_3C . Cementite has carbon content of 6.67% by weight. It is the hardest (BHN 700) and most brittle phase. It is found with ferrite in pearlite. Usually it appears at grain boundaries in high carbon steels. Its crystal structure is orthorhombic. It dissolves only at high temp. It has melting point around 1550°C. It possesses low tensile strength (34 MPa approx) but high compressive strength. Under certain conditions, cementite decomposes to form free carbon called as graphite.

(E) **Ledeburite:** It is a eutectic consisting of austenite and cementite. It is observed in cast irons containing 4.3% carbon at 1147 °C.

Critical temperatures:

These are defined as the temperatures at which a phase change occurs during heating and cooling. Various critical temperatures are given as follows:

1. A_1 : During heating at this temp; pearlite transforms to austenite. This transformation occurs at a constant temperature of 723 °C called as eutectoid temp. It has importance in various annealing processes. It is called as lower critical temperature line.
2. A_2 : This line indicates Curie temperature. During heating, the ferrite which is magnetic becomes non-magnetic above this line.
3. A_3 : This line, in hypoeutectoid steels shows the completion of ferrite to austenite transformation during heating. The decline from the temp axis with increasing carbon content. It starts at 910 °C with zero percent carbon and ends at 727 °C with 0.8% carbon. For various heat treatments, the hypoeutectoid steels should be heated above this line. This line represents upper critical temperature for ferrite.
4. A_{cm} : At this line, in hypereutectoid steels the cementite to austenite transformation is completed during heating. This line shows increasing slope from 727 °C to 1148°C. It starts at 727 °C with 0.8% carbon and ends at 1148 °C with 2% carbon. For certain Heat treatments, which involve dissolution of cementite, hypereutectoid steels are heated above this line. This line represents upper critical temperature for cementite.

During heating or cooling at faster rates, the transformation occurs at higher or lower temperature respectively. This shifts the equilibrium of critical temperature lines. These lines are denoted by letter C; from French word *chauffage* - means heating and by letter r; from the French word - *refroidissement* - means cooling, e.g. AC_1 , AC_3 , during heating. Ar_1 , Ar_3 - during cooling.

Reference books:

1. Heat Treatment (Principles and Techniques) - By T. V. Rajan. CP. Sharma & Ashok Sharma, Prentice - Hall of India Pvt. Ltd., Tenth Printing (Revised Edition) Dec 1999.
2. Introduction to Physical Metallurgy - By Sidney H. Avner. Mc-GRAW HILL International Edition. 14th Printing. 1988.

Quiz:

1. Explain the classification of steels in the context of Fe-Fe₃C equilibrium diagram.

2. The mechanical properties of steels are structure dependent— Comment on it.

3. What are the critical temperatures? Explain their significance.

4. Draw typical micro-structures of 0.2%, 0.4%, 0.6% and 0.8% carbon steel. Comment on the amount of phases present.

5. What are the liquidus and solidus curves in an equilibrium diagram?

6. Discuss allotropic change of iron during cooling to room temperature from molten iron.

7. With respect to iron-iron carbide diagram explain;

- A) slow cooling of 0.35 % carbon steel and
- B) Slow cooling of 1.5% carbon steel.

Date:	Sign:	Grade
--------------	--------------	--------------

OPTICAL MICROSCOPE

Experiment No:-3

Date:

Objective: To study optical (metallurgical) microscope.

Theory:

Microscope is an important tool for a mechanical / metallurgical engineer. Metallurgical Microscope is very helpful in determining the size, shape and distribution of various phases, including inclusions in metals. Grain size determination is also made with the help of metallurgical microscope. All these studies have a great bearing on the mechanical properties of metals. No structure-property correlation can be made without the help of metallography.

For study of metallurgical microstructures, microscope is used. Various microscopes used are as follows:

- Optical microscope,
- Electron microscope
 - Scanning electron microscope.
 - Transmission electron microscope etc.

A metallurgical microscope differs from a biological microscope in following respect:

- It uses an external sources of light.
- Metallurgical samples are opaque to light, and
- Reflected light is used in metallurgical microscope.

Working principle:

A horizontal beam of light from a suitable source is diverted downward by a plane glass reflector through the objective lens on etched surface of specimen. The light gets reflected back and passed through the objective and then eyepiece. By observing through the eyepiece, an enlarged image of illuminated area may be studied. An aperture diaphragm opening should be optimum to observe the structure fully.

Construction:

It consists of (a) main frame (b) eye piece lens (c) objective lens (d) revolving nose piece for objectives (e) knobs for coarse and fine adjustment (f) light source (g) light intensity knob (h) specimen stage with x and y direction movement and (i) filters.

All the above parts are fitted on the main frame. The lens from which the microstructure is observed is called an eyepiece. Objective lens is the lens near the specimen. Revolving nosepiece consist of objective lens of different magnification. The coarse and fine adjustment knobs are used to focus the image sharply. The light source provides illumination. For adjustment of brightness, the light intensity knob is used. The specimen may be scanned without touching it. by using x and y direction movement knobs. Better contrast may be obtained by adding or removing some of the filters.

1. **Halogen lamp:** It is used as a light source. This light source is especially suitable for color photomicrography.
2. **Intensity variation knob:** Intensity of halogen lamp can be adjusted by this knob.
3. **Aperture Diaphragm:** It is placed in front of the lamp or condenser. Used to control resolving power, contrast and depth of the focus.
4. **Filters:** They are required to modify the light for optimum visual examination or photomicrography. Green filters are used for observation and blue filters are used for photography.
5. **Plane glass reflector:** Used to divert the- horizontal beam of light coming from light source onto the specimen. It also transmits the reflected light from the specimen to eye piece.
6. **Objective:** It forms the primary image. In conjunction with the field lens of eyepiece. It collects as much light as possible coming any point on the specimen and combines this light to form the image. The numerical aperture is a measure of the light collection capability of the objective.
7. **Stage mounting table:** It is used to hold the specimen. Separate knob is provided for X-Y movement of the table.
8. **Focusing (Fine and Coarse):** From these one can move the stage of the Microscope Up and Down in respective type for getting clear image.
9. **Eyepiece:** It forms the second capital system. They are used to enlarge the primary image formed by the objective.
10. **Stage/mounting table:** It is used to hold the specimen. Separate knob is provided for x-y movement of the table.
11. **CCD camera:** CCD stands for "Charge Coupled Device. A CCD camera uses the same technology as the popular digital cameras used for everyday photography. They are used to transfer virtual image visible in the eye piece to computer.
12. **Frame Grabber Card:** A device that lets you captures individual frames out of a video camera or off a video tape.

Photographic attachment may be used to make the permanent record of microstructure. A close circuit television attachment is also possible so that more than one person may observe the structure at a time. A special quality metallograph with a projecting screen is used with video camera and suitable software system called as image analyzer. This helps in calculating volume fraction of various phases, nodule count, number of nodules etc. in nodular cast irons.

The resolving power of an objective lens is its ability, which makes it possible to see distinctly two separate lines in a structure. Therefore, magnification by microscope is increased to see distinctly the details of an object.

The resolution δ is related to wavelength λ of illumination, refractive index μ of medium between the lens and specimen and the numerical aperture by the equation,

$$\delta = \frac{0.5\lambda}{\text{Numerical aperture}} = 0.5\lambda / \mu \sin \alpha$$

Where α is half the angle subtended by the maximum cone of light rays coming to the objective lens? The numerical aperture is the quantitative measurement of light gathering power of an objective lens.

Magnification depends on the focal length. The shorter the focal length of the lens, the greater will be the magnification of structure. The total magnification of a microscope is obtained by multiplication of the magnifying powers of the eyepiece and objective lenses used at that instant. The maximum magnification that can be obtained with the optical microscope is about 2000X. The principal limitation is the wavelength of the visible light, which limits the resolution of the fine detail in the metallographic specimen.

Two types of metallurgical microscopes widely used for metallographic study are: *Vertical or upright bench microscope* and *Inverted bench microscope*. These are based on orientation of the polished plane of the specimen during observation. One added feature of inverted bench microscope is that it requires only one flat and polished surface. The other surface may not necessarily be flat.

Bright field illumination gives un-etched (or cathodic) area of the specimen as bright and etched (or anodic) area of specimen as dark. This means, in this type of illumination, single-phase metal and alloy shows bright grains and dark grain boundaries. This occurs because the reflected light is regathered by the lenses while scattered light does not get recollected. Bright field illumination is normally used to study the metallographic structure.

Dark field illumination gives exactly reverse feature to bright field illumination. In this type of illumination, only scattered light is recollected, while the reflected rays are blocked. This produces very strong image contrast. Under such illumination, it is possible to see features, which are not visible using bright field illumination. However, the photomicroscopy becomes difficult in this illumination.

Auxiliary techniques:

Several special instruments, as mentioned below, can be used with optical microscope to obtain additional information:

- Micro-hardness testing,
- Hot stage microscopy, and
- Comparison microscope.

Applications:

Metallography is used to study the following:

1. Size, shape and distribution of various phases.
2. Grain size determination and its distribution.
3. Prediction of probable mechanical properties.
4. Presence of secondary phases and its distribution.
5. Non-metallic inclusions,
6. Segregation of elements,
7. Heterogeneous conditions,

- Routine testing during production.
- Failure analysis, and
- Research and development of new alloys and processes.

1. Heat Treatment (Principles and Techniques) - By T.V. Rajan, CP. Sharma & Ashok Sharma. Prentice -Hall of India Pvt. Ltd., Tenth Printing (Revised Edition) December - 1999.
2. Introduction to Physical Metallurgy - By Sidney H. Avner. Mc-GRAW HILL International Edition, 14th Printing - 1988.

1. State the principle of an optical (metallurgical) microscope.

2. State the parts of a metallurgical microscope and their functions briefly.

3. What is metallography? Discuss the importance of metallography.

4. What is the resolving power of an objective lens?

5. What do you mean by the magnification of a metallurgical microscope?

6. Why grain boundaries are observed darker under microscopic examination with bright field illumination?

Date:

Sign:

Grade:

PREPARE A SPECIMEN FOR MICROSCOPIC EXAMINATION

Experiment No:-4

Date:

Objective: To prepare a specimen for microscopic examination.

Introduction:

Metallography consists of the microscopic study of the structural characteristics of a metal or an alloy. It is possible to determine size, shape and distribution of various phases and inclusions, which have a great effect on the mechanical properties of the metal. The microstructure will reveal the mechanical and thermal treatment of the metal, and it may be possible to predict its expected behavior under a given set of conditions. Experience has indicated that success in microscopic study depends largely upon the care taken in the preparation of the specimen. The most expensive microscope will not reveal the structure of a specimen that has been poorly prepared. The procedure to be followed in the preparation of a specimen is comparatively simple and involves a technique, which is developed only after constant practice. The ultimate objective is to produce a flat, scratch-free, mirror-like surface.

Tools & Instruments:

- Abrasive cut off machine or hacksaw.
- Belt sander or abrasive grinding m/c.
- Mounting press.
- Polishing machine.
- I lot air drier.

Materials:

- specimens to be prepared;
- Synthetic plastic material e.g. Bakelite, Lucite, acrylic, polystyrene.
- Emery papers of grade 100,200,300,400,500.600 and 800. (Silicon carbide)
- Etchant e.g. nitric acid (nital), picric acid (picral) etc.
- Cotton plugs.

Experimental Procedure:

1. Sampling: The choice of a sample for microscopic study may be very important. If a failure is to be investigated, the sample should be chosen as close as possible to the area of failure and should be compared with one taken from the normal section.

The sample should be taken from the longitudinal section, if the effect of rolling, extrusion or wire drawing process to be studied. For observation of case hardened steels, edges of the sample should be carefully preserved. Sectioning methods include fracturing, shearing, sawing, abrasives cutting and electric discharge machining. Fracturing is recommended for extremely brittle materials. It is carried out by blows of hammer. Less brittle materials can be cooled in liquid nitrogen before breaking to obtain a flatter surface. Low carbon steel sheets and other soft materials can be cut to size by shearing. Sawing is widely used for sectioning. It may be manual or power saw. To cut larger

pieces, power saw is used. Manual sawing is used for less hard materials. Abrasive cutting method is used for very hard materials such as hardened steels. For this, consumable or non-consumable cut-off wheels are used. Silicon carbide impregnated wheels are used for nonferrous and non-metals. Alumina is recommended for ferrous metals. Coarse grain wheels are used to cut heavier sections while fine grain wheels are recommended for delicate materials, e.g. thin wall tubes. For metallographic purpose 60 to 120 grit sizes are used. The coolant used contains water-soluble oils with rust inhibitor additives and foaming agents. Wire saws are used to cut very thin sections. The sectioning of metallographic specimens can also be performed on electric discharge machine.

2. Rough grinding: Whenever possible, the specimen should be of a size that is convenient to handle. A soft material may be made flat by slowly moving it up and back across the surface of a flat smooth file. The soft or hard specimen may be rough ground on a belt sander, with the specimen kept cool by frequent dipping into water during grinding operation. In all grinding and polishing operations the specimen should be moved perpendicular to the existing scratches. This will facilitate recognition of the stage when the deeper scratches have been replaced by shallower ones characteristics of the finer abrasive. The rough grinding is continued until the surface is flat and free of nicks, burrs, etc. and all scratches due to the hacksaw or cutoff wheel are no longer visible.

3. Mounting: Small and odd shaped components are mounted to facilitate handling during preparation. Sharp edges and corners are eliminated to avoid damage to polish papers and cloth. Mounting provides uniform sized and shaped specimens which are convenient to prepare, view and store. Standard mountings are usually of 25mm diameter and 12mm thickness. Proper thickness of mount is necessary because thin mounts are difficult to handle while very thick mounts are difficult to hold flat during polishing. Mechanical mounting devices are used to prepare transverse or longitudinal sheet surfaces. For this purpose, specially designed metal clamps are used. Plastic mounting materials can also be effectively used. Some of the plastic materials require heat and pressure while others are castable at room temperature. Mounting is completed with help of specimen mounting press. This is done in temperature range 135 - 170°C and pressure range 2500 - 4200 psi within 5 to 12 minutes.

4. Intermediate polishing: After mounting, the specimen is polished on a series of emery papers containing successively finer abrasives. The first paper is usually 100 then 220, 320, 400, 500, 600 and finally 800. The intermediate polishing operations using emery papers are usually done dry; however in certain cases such as preparation of soft materials, silicon carbide abrasive may be used.

5. Fine polishing: Fine polishing is done with single or double disc polishing machine. The time consumed and the success of fine polishing depends largely upon the care that was exercised during the previous polishing steps. The final approximation to a scratch-free surface is obtained by use of a wet rotating wheel covered with a special cloth that is charged with carefully sized abrasive particles. The gamma form of aluminum oxide for ferrous and copper-based materials; cerium oxide for aluminum, magnesium and their alloys is used for fine polishing. Other final polishing abrasives often used are diamond paste, chromium oxide and magnesium oxide. The cloths used for polishing are silk, broad cloth, billiard cloth, canvas duck, velvet etc. A properly polished sample will show only the non-metallic inclusions and will be of scratch-free.

6. Etching: This is accomplished by use of appropriate reagent which subjects the polished surface to chemical action. The purpose of etching is to make visible the many structural characteristics of the metal or alloy.

Etching is carried out by swabbing or by immersion method. Swabbing is generally carried out for certain metals in which gas evolution is observed due to reaction with etchant. It consists of keeping swabbing the polished surface with cotton saturated with etchant. After desired etching time, the surface of the sample is thoroughly rinsed under water and dried with hot air drier. In immersion method, the sample is dipped in etchant for specified time. Then it is washed and dried. Etching is normally continued until the mirror finish of sample becomes dull.

In alloys composed of two or more phases, the components are revealed during etching by a preferential attack of one or more of these constituents by the reagent, because of difference in chemical composition of the phases. In uniform single-phase alloys or pure metals, contrast is obtained and grain boundaries are made visible because of difference in the rate at which various grains are attacked by the reagent. This difference in the rate of attack is mainly associated with the angle of different grain sections to the plane of the polishing surface. Because of the chemical attack by the etching reagent, the grain boundaries will appear as valley in the polishing surface. Light from the microscope hitting the side of these valleys will be reflected out of the microscope, making the grain boundaries appear as dark lines.

TABLE: Important Etchants

Sr. No.	Name	Composition	Applications
1.	Nital	HNO ₃ (Cone): 2-10 ml. Ethyl alcohol : 90 ml.	Used for plain carbon steels, low alloy steels, cast iron etc.
2.	Picral	Picric acid 4 ml. Ethyl alcohol : 96 ml.	
3.	Acid ferric chloride	FeCl ₃ : 10 gm. HCL- 30 ml. Water : 120 ml.	For nonferrous metals. Copper base alloys.
4.	Ammonium Hydroxide + H ₂ O ₂	NH ₄ OH: 10 ml. H ₂ O ₂ : 10 ml.	For brass, German silver etc.

Reference books:

1. Heat Treatment (Principles and Techniques) - By T.V. Rajan, CP. Sharma & Ashok Sharma, Prentice -Hall of India Pvt. Ltd., Tenth Printing (Revised Edition) December - 1999.
2. Introduction to Physical Metallurgy - By Sidney H. Avner, Mc-GRAW HILL International Edition, 14th Printing - 1988.

Quiz:

1. Explain etching mechanism.
2. Write short note on mounting of sample.

4. Explain the term metallography.

5. What is the importance of sampling?

Date:	Sign:	Grade:
--------------	--------------	---------------

Mounting of Specimen

Experiment No:-5

Date:

Objective: Mounting of specimen using hot mounting press.

Equipment: Mounting press with die & punch.

Materials: Bakelite powder, metal sample.

Theory:

Metallographic and microstructure analysis almost unanimously proffered mounted samples to those which provides for uniformity in size which makes handling and storage easier. While providing for improved samples edge retention & personal injury due to sharp corners & edges becoming engaged in rotating grinders & polishes.

Small and odd shaped compounds are mounted to facilitate handling during preparation. Mounting provides uniform size and shapes. Standard mountings are usually of 25 mm diameter and 12 mm thickness. Proper thickness of mounts is necessary because thin mounts are difficult to handle. However, thick mounts are difficult to hold flat during polishing. Mechanical mounting devices are used to prepare transverse or longitudinal sheet surface. For this purpose, specially designed metal clamps are used plastic mounting materials can also be effectively used. Mounting is completed with help of specimen mounting press. This is done in temperature range 135 -170° C.

Equipment for compression mounting must produced required heat and pressure for proper mounting of the sample.

- i) **Pressure:** Pressure applied is for means of hydraulic action which required a minimum physical effort.
- ii) **Moulding:** 25 mm Ø mould move of heat treated die steel.
- iii) **Heating:** approximately 800 w heats controlled by energy regular operating or 20v singles phase supply.
- iv) **Cooling:** by finned aluminum cast collar around the mould for rapid cooling rate put a wet cloth around the aluminum collar.
- v) **Ejection:** ejection is by means of a groove which is situated on the middle plate, the bakelite specimen mould is kept on top of it and pressure is applied which force the mould pin to eject out the specimen. Two aluminum pins are also supplied with the pressure.

Procedure:

1. Place the spacer at the centre of the insert plate and then place the specimen to be mounted with downward on the spacer.

2. Brings the mould on the top of the surface spacer and slide it down to over the spacer. Ultimately resting the mould on the top of the insert plate.
3. Pour the thermosetting powder in to the mould through a funnel to already of two thirds of the mould height.
4. Slow introduce the mould pin side the mould to the powder.
5. Side the insert plate with the mould and mould line on the movable centre stage plate.
6. Close the release valve and pump with handle when the middle plate will rise. Continue pumping until the pressure gauge register about 1000/bs. Sq. inch (210kg/sq mm)
7. Swing in the electric heater around the mould set the thermostat to full position and switch on.
8. Introduce thermometer in thermometer wall provided on the top plate and observe the temperature.
9. As the temperature reaches the maximum temperature predetermined by the thermostat the indicator lamp will go off.
10. Swing out the heater and place the cooler in position around the mould for rapid cooling put a piece.
11. Allow the temperature to fall below 80°C and relate the pressure slowly.
12. When pressure is completed released the mould from the insert plate and put in the ejection seat and pump. When the mould pin enter the mould and will press out the bakelite specimen mount that has been set.
13. Clean inside of the mould release grease.
14. Clean the spaces and mould pin and apply greases.
15. Insert the moulding pin in the mould and the machine is now ready for the next mould.

Reference books:

1. Introduction to Physical Metallurgy - By Sidney H. Avner, Mc-GRAW HILL International Edition.
2. Heat Treatment (Principles and Techniques) - By T.V. Rajan, CP. Sharma & Ashok Sharma, Prentice Hall of India Pvt. Ltd.

Quiz:

1. Why mounting of sample is required?

4. Why an optimum thickness of mounting is recommended?

Date:	Sign:	Grade:
--------------	--------------	---------------

MICROSTRUCTURE OF FERROUS MATERIALS

Experiment No:-6

Date:

Objective: To study the microstructure of ferrous materials.

Materials: Gray cast iron. Nodular cast iron, Bearing Steel (En31) etc.

Tools & Instruments:

1. Abrasive cut off wheel or hacksaw m/c.
2. Belt sander or abrasive grinding m/c. or smooth file.
3. Mounting press.
4. Polishing machine.
5. Hot air drier.
6. Metallurgical microscope.
7. Screen projector, and
8. Close Circuit T.V.

Gray Cast Iron: It is obtained by cooling the molten metal slowly during solidification. A large portion of its carbon is present in free state as graphite flakes. A typical gray cast iron contains: 2.5 to 3.5 % C, 1.4 to 2.8 % Si, 0.5 to 0.8 % Mn, 0.1 to 0.9 % P, and 0.06 to 0.12 % S.

Fracture surface of gray C.I. appears gray because of the presence of graphite. Carbon, Silicon, and Phosphorous affect the tensile strength of cast iron. [Tensile strength of gray C.I. varies from 100 to 340 Mpa, Compressive strength varies from 600 to 700 Mpa, and Hardness varies from 150 to 250 BHN].

White Cast Iron: In white C.I. carbon is present in combined form, i.e., in the form of cementite (Fe_3C). Fractured surface of broken piece of this type of casting has white appearance. Cementite is present as a continuous interdendritic network. This makes the cast iron hard and wear resistant but brittle. As machinability is poor, it has limited applications. Chemical composition typical white C.I. 2.5 to 3.5 % C, 0.4 to 1.5 % Si, 0.4 to 0.6 % Mn, 0.1 to 0.4 % P, 0.15 % S. Their mechanical properties are: T.S. - 140 - 490 Mpa, C.S. = 1400 - 1750 Mpa, and Hardness = 375 - 600 BHN.

Experimental procedure:

- 1) Cut the specimen in convenient size that can be handled.
- 2) Rough grind it to make two opposite surfaces flat and parallel.
- 3) Mount the specimen if required.
- 4) Carry out intermediate polishing with silicon carbide abrasive papers successively on 100,200,300,400,500,600.
- 5) Fine polish the specimen on disc polishing machine with applying fine abrasive powder; aluminum oxide.
- 6) Etch the specimen with etching reagent 5% nital or 5% picral.
- 7) Wash and dry the specimen.
- 8) Examine the microstructure under the metallurgical microscope.
- 9) Draw the microstructure and write your comment on each.

Bearing Steel (Through hardening grade)

Condition: Hot rolled, Mechanical

Treatment: None

Etchant: Nital

Magnification: 100X

Chemical composition:

En-31 (British Std.)

C = 0.90-1.20%
Si = 0.10-0.35%
Mn=0.30-0.70%
Cr=1.0-1.60%
S =0.06% Max.
P =0.06%Max.

Grade: ASTM A 295
AISI/SAE 52100

C =0.98-1.10%
Si = 0.15-0.35%
Mn =0.25-0.45%
Cr =1.30-1.60%
S =0.025% Max.
P =0.025%Max.

IS 4398 -1994
Grade: 104 Cr 6.

C =0.98-1.10%
Si =0.15-0.35%
Mn=0.25-0.45%
Cr =1.30-1.40%
S =0.025%Max
P =0.025%Max.

Material: En8
(British Standard)

C =0.35-0.45%
Si = 0.15-0.35%
Mn =0.60-1.00%
S =0.06% Max.
P =0.06% Max.

In American Standard
Nearest Equivalent Std. of En8
is AISI/SAE 1040 Grade

C = 0.37-0.44%
Si =0.20-0.35%
Mn =0.60-0.90%
S =0.025%Max.
P =0.025% Max.

Heat Treatment of bearing steel made out of SAE 52100

Annealing (Spheroidization) temp	- 780 to 790 C
Hardening temp.	- 830 to 850 C
Quenching medium	- Oil (Metaquench-42)
Tempering temperature	- 160-180C
As-quenched hardness.	- 62 HRC minimum.
Hardness after tempering	- 60 to 62 HRC.

Reference books:

1. Heat Treatment (Principles and Techniques) - By T.V. Rajan, CP. Sharma & Ashok Sharma, Prentice -Hall of India Pvt. Ltd.. Tenth Printing (Revised Edition) December - 1999.
2. Introduction to Physical Metallurgy - By Sidney H. Avner. Mc-GRAW fill I International Edition, 14th Printing - 1988.

Quiz:

1. What do you mean by "Seasoning of cast iron"?

2. What are the advantages of cast iron over steel?
3. Why are the alloys of iron and carbon with carbon percentage 2.0 to 6.67 called as cast iron?

4. Draw microstructure of the following cast irons and comment on it.
 - a. Gray cast iron
 - b. Nodular cast iron
 - c. White cast iron

5. Draw microstructure of the following ferrous materials and comment on it.
- a. Low carbon steel
 - b. Medium carbon steel
 - c. Stainless steel
 - d. Bearing steel
 - e. En-8.

Date:	Sign:	Grade:
-------	-------	--------

QUENCHING MEDIA FOR HARDENING OF STEEL

Experiment No:-7

Date:

Objective: To examine the effect of quenching media on hardening of steel.

Tools & Instruments:

- Quenching media (brine, water, oil and air).
- Quenching bath.
- Furnace.
- Rock well hardness testing machine.

Theory:

As applied to the heat treatment of steels, quenching is a process of rapid cooling of steel from austenizing temperature. Quenching results in the transformation of austenite into martensite (a non-equilibrium constituent having body center tetragonal structure). This highly stressed structure increases hardness of steel. Under ideal conditions, all the heat absorbed by the medium should reject to the surroundings immediately. The effectiveness of a quenching process largely depends on the characteristics of the quenchant used. In addition to it, some other factors such as chemical composition of the steel, design of steel component, and surface conditions of steel component also control the efficiency of the quenching process.

The removal of heat during quenching is complex in the sense that, the heat is removed in the three stages. When heated steel is quenched in a suitable medium, it shows temperature gradient between the surface and the core of steel. The surface cools down more rapidly than does the core. As a result of this the following stages are observed.

(a) Vapour blanket stage:

Due to high temperature of work piece the quenching medium gets vaporized at the surface of metal and forms a thin vapor film (blanket). This vapour film, being poor conductor of heat, checks further cooling of the work piece. The work piece is cooled at the stage by conduction and radiation through the vapor film.

(b) Vapour transport cooling stage or liquid boiling stage:

The vapor film is suitable up to 400°C. As soon as the vapour film is broken, the quenchant comes in contact with surface of the work-piece and is immediately pushed away from it in the form of bubbles. Fresh coolant now comes in contact with the work piece surface and the process is repeated. Very rapid cooling takes place at this stage as the quenchant is always in contact with the surface of the work piece.

(c) Liquid cooling stage:

In this stage the surface temperature of the work-piece reaches the boiling point of the quenchant. Cooling at this stage takes place by both conduction and convection processes. The rate of cooling is the slowest at this stage.

The quenching medium must show effective heat removal during quenching. It should possess the following characteristics:

1. High initial cooling rate to avoid transformation at nose region.
2. Slow cooling rate below nose to minimize cracking and distortion.

The various quenching mediums used are as following in the decreasing severity of quenching.

1. Water solution of 10% sodium chloride (brine).
2. Tap water.
3. Fused or liquid salt.
4. Soluble oils.
5. Oil. and
6. Air.

Alloy steels have lower critical cooling rate (CCR) and hence, they can be hardened by air cooling. Oil quenching is used for high carbon steels as they show higher CCR. Medium carbon steels have very high CCR so; water or brine quenching is required. Even water or brine cooling cannot harden extremely low carbon steels.

Experimental Setup: Cooling baths containing different quenching medium are required.

Experimental Procedure:

1. Prepared specimens from ms of 1 inch diameter and 4 inches long.
2. Heat this specimen in furnace for 30 minutes for austenitic transformation. This temperature depends on the carbon content of the steel.
3. Remove specimens from furnace and immerse in different quenching baths for about 5 to 10 minutes.
4. Prepare the surface of specimen.
5. Measure hardness of each specimen with the Rockwell hardness-testing machine.
6. Tabulate these observations.

Observation table:

Sr. No.	Quenching media.	Hardness before Quenching.	Hardness after quenching
1			
2			
3			
4			
5			

1. State the major disadvantage associated with water quenching.
2. Water is the most commonly used quenching medium. Why?

3. What is CCR? What is significance of CCR to obtain hard martensitic structure?

4. Explain the mechanism of heat removal during quenching.

5. Explain the transformation of austenite to martensite.

Date:	Sign:	Grade:
-------	-------	--------

HARDENABILITY OF STEEL

Experiment No:-8

Date:

Objective: To find hardenability of steel.

Tools & Instruments:

1. Jominy End-quench apparatus.
2. Water jet setting gauge.
3. Rockwell hardness testing machine.
4. Standard specimen of 1" diameter and 4" long with collar at one end.
5. Muffle Furnace.

Theory:

Hardenability is the ease with which a steel piece can be hardened. It is defined as the depth upto which 50 % martensite or hardness of Rc54 is observed. The hardness of hardened steel is measured on its surface. The surface shows higher hardness, which decreases towards the center of steel specimen. This variation in hardness along its cross section may be termed as Hardenability. It is not related to the maximum hardness, and the term hardness and hardenability should be clearly distinguished. Hardenability is very important property in heat treatment of steel. It provides following information in heat treatment:

- Maximum hardness that can be obtained on the surface of steel.
- Depth & distribution of hardness across a cross section,
- Required cooling rate or quenching medium,
- Stress level on surface etc.

Hardenability depends on the following factors:

- Composition of steel.
- Austenitic grain size.
- Homogeneity of austenite.
- Non-metallic inclusions in the austenite, and
- Presence of alloying elements (i.e. undissolved carbides and nitrides in the austenite).

Besides this, the coolant used for quenching, the size of the specimen, and the criterion used for assessment of hardenability also affect the extent of hardenability.

Hardenability can be measured by any one of the following methods:

1. Jominy end quench test,
2. Grossman's critical diameter method,
3. Fracture test, and
4. Hardenability estimation from chemical composition.




Fig 1: Variation of hardness along the diameter of a quenched cylindrical test-piece.

Experimental setup:




Fig 2: Experimental setup for Jominy end quench test.

Experimental procedure:

1. Preparation of standard test-piece of 1 "diameter and 4" length.
2. Heat the specimen to proper austenizing temperature and allow soaking for sufficient time in the furnace.
3. Transfer the specimen immediately in a fixture (as shown in figure 2).
4. Spray water on the lower end of the specimen. The flow of water should be such that it forms an umbrella shape and continue for 10 minutes.
5. Take out the specimen from fixture.
6. Measure the hardness at 1/16" interval from the quenched end.
7. Tabulate these values and plot a graph of hardness v/s distance from the quenched end. This is a hardenability curve.

Observation table:

1. Specimen Material : _____
2. Composition : _____
3. Specimen size : _____
4. Hardness before quenching : _____
5. Temp, and soaking time : _____

Experiments in Material Science & Metallurgy: Semester III

Sr. No.	Distance from the quenched end. (mm)	Hardness (HRC)	Sr. No.	Distance from the quenched end. (mm)	Hardness (HRC)
1			17		
2			18		
3			19		
4			20		
5			21		
6			22		
7			23		
8			24		
9			25		
10			26		
11			27		
12			28		
13			29		
14			30		
15			31		
16			32		

Conclusion:

If hardness is in between 60 HRC to 50 HRC → Through hardenable steel.
 60 HRC to 40 HRC → Deep hardenable steel.
 60 HRC to 30 HRC → Shallow hardenable steel.

Reference books:

1. Heat Treatment (Principles and Techniques) - By T.V. Rajan, CP. Sharma & Ashok Sharma, Prentice -Hall of India Pvt. Ltd., Tenth Printing (Revised Edition) December 1999.
2. Introduction to Physical Metallurgy - By Sidney H. Avner, Mc-GRAW HILL International Edition, 14th Printing - 1988.

Standards : The test has been standardized by ASTM, SAE. and AISI. Details pertaining to the testing procedure may be obtained by referring to ASTM Designation A225 - 48T End-Quench test.

Quiz:

1. State and explain the factors influencing Hardenability of steel.
2. Does carbon content affect the Hardenability of steel? What is the importance of chemical composition of steel with respect to Hardenability?
3. Give any four etching reagents use in microscopy.

4. Define and explain the term “Severity of quench”

5. Difference between hardness and Hardenability.

Date:	Sign:	Grade:
--------------	--------------	---------------

EFFECT OF SECTION SIZE ON MATERIAL HARDNESS

Experiment No:-9

Date:

Objectives: To determine the effect of section size on hardness of the material developed during quenching.

Tools & Instruments:

1. Muffle Furnace
2. Abrasive cut-off machine
3. Quenching bath
4. Hardness tester
5. Lathe machine

Theory:

Quenching refers to the process of rapidly cooling metal parts from the austenitizing or solution treating temperature typically from within the range of 815 - 870°C for steel. Most steel including carbon, low alloy, & tool steels are quenched to produce controlled amount of martensite in the microstructure.

The selection of the quenching medium depends on the hardenability of the particular alloy, the section thickness and shape involved, and cooling rates needed to achieve the desired microstructure. Rate of heat transfer from a part being quenched may be affected by oxidation of the surface, section thickness, quenching medium characteristics, agitation of the quenching bath etc.

Oxidations of the surface can either increase or decrease the heat transfer rate depending on the thickness of the oxide developed. Agitation refers to liquid quench medium movement relative to part. Agitation is usually obtained by moving the part in the liquid, but in some cases it is obtained by moving the parts in the liquid. Agitation has an extremely important influence on the heat transfer. Agitation causes mechanical disruption of the vapour blanket and a faster transition to liquid boiling stage. Increasing agitation usually produces a shorter vapour blanket stage and faster cooling rate in all three stages of cooling. The cooling rates are also functions of the thickness and geometry of the part.

Section size effect:

The effect of section size on cooling rates for varying cross section of the steel is illustrated in Fig.1. Cooling rates dramatically decrease with increase in section thickness. With heavy section, the cooling rate is limited by the rate of heat conduction from the interior to the surface. Rapid cooling of the center of an extremely large section is impossible by any quenching method because of the mass-effect. Therefore, when deep hardening a heavy section, it is necessary to use an alloy steel with higher hardenability.

The change in section thickness of parts affects the shape of cooling rates. Consequently, the hardness and strength of parts being quenched may get affected

Experimental Procedure:

1. Prepare a test piece as per dimension shown in Fig. 1.
2. Heat the test piece in furnace for 30 minutes at austenizing temperature.
3. Remove the test-piece from furnace quickly and immerse in quenching bath (water/oil).
4. Measure the hardness at center and at surface for different section.
5. Tabulate these observations.
6. Plot graph between variation in hardness and section thickness




Fig.1 Test piece for experiment

Observation Table:

Material	Section thickness (mm)	Hardness at surface	Hardness at center	Variation in hardness at surface and center

Conclusion(s):

Reference books:

1. ASM Hand Book, Titled 'Heat Treating'. Volume 4. Chapter: Quenching of Steel Page No. 67 - 75
2. Heat Treatment (Principles and Techniques) - By T.V. Rajan, CP. Sharma & Ashok Sharma. Prentice -Hall of India Pvt. Ltd., Tenth Printing (Revised Edition) December - 1999.

Quiz :

1. In heat treatment, why austenitizing of a component (steel) is required before hardening?
2. List the factor affecting the rate of heat transfer during quenching of steel.

6. Briefly discuss the advantages and disadvantages of oil as a quenching medium.

Date:	Sign:	Grade:
--------------	--------------	---------------

**ULTRASONIC METHOD FOR THE DETECTION OF SURFACE AND
SUBSURFACE FLAWS**

Experiment No:-10

Date:

Objective: To study ultrasonic method for the detection of surface and subsurface flaws.

Tools & Instruments:

1. Electronic signal generator,
2. Transducer (Probe or search unit),
3. Echo-signal amplifier,
4. Display device (oscilloscope),
5. Calibration blocks,
6. Couplant etc,

Working principle:

In ultrasonic inspection method, beams of high frequency sound waves are introduced into materials for detection of surface and subsurface flaws in the material. The sound waves travel through the materials with some attendant loss of energy (attenuation) and are reflected at interfaces. The reflected beam is displayed and then analyzed to define the presence and location of flaws or discontinuities.

Major Variable in Ultrasonic Inspection:

- Frequency of the ultrasonic wave.
- Acoustic impedance.
- Angle of incidence if ultrasonic wave.
- Critical angles.
- Beam intensity.

Basic Inspection Methods:

The two methods of ultrasonic inspection are:

1. Transmission method: It involves only the measurement of signal attenuation.
2. Pulse echo method: It can be used to measure both transit time and signal attenuation.

The pulse echo method, which is the most widely used ultrasonic method, involves the detection of echoes produced when an ultrasonic pulse is reflected from a discontinuity or an interface of a test piece. This method is used in flaw location and thickness measurements. Flaw depth is determined from the time of flight between the initial pulse and the echo produced by a flaw. Flaw depth might also be determined by the relative-transit time between the echo produced by a flaw and the echo from the back surface.

Advantages:

- Superior penetrating power, which allows the detection of flaws deep in the part.
- High sensitivity, permitting the detection of internally small flaws.

- Greater accuracy than other nondestructive methods in determining the position of internal flaws, estimating their size, and characterizing their orientation, shape, and nature.
- Only one surface needs to be accessible.
- Operation is electronic, which provides almost instantaneous indication of flaws.
- Portability
- Non hazardous to operation or to nearby personnel.
- Provides an output that can be processed digitally by a computer to characterize defects and to determine material properties.

Disadvantages:

- Manual operation requires careful attention by experienced technicians.
- Extensive technical knowledge is required for the development of inspection procedure.
- Rough, irregular shape and in homogeneous parts are difficult to inspect.
- Couplant are needed to provide effective transfer of ultrasonic wave energy between transducers and being inspected.
- Discontinuities that are present in a shallow layer immediately beneath the surface may not be detectable.
- Reference standards are needed, both for calibrating the equipment and for characterizing.

Applications:

- Mill component rolls, shafts, drivers and press columns.
- Power equipment: turbine, forging, generator rotors, pressure piping, pressure vessels etc.
- Jet engine parts: turbine and compressor forging, and gear blocks.
- Air craft components: Forging stock, frame section etc.
- Machinery materials: Die blocks, tool steels and drill pipe.
- Rail road parts: Axles, wheels, track and welded rail.
- Automotive parts: Forging, ductile castings, welded components, bearings etc.

Reference books:

1. Heat Treatment (Principles and Techniques) - By T.V. Rajan. CP. Sharma & Ashok Sharma, Prentice -Hall of India Pvt. Ltd., Tenth Printing (Revised Edition) December - 1999.
2. Introduction to Physical Metallurgy - By Sidney H. Avner. Mc-GRAW HILL International Edition, 14th Printing - 1988.

Quiz:

1. What do you mean by attenuation?

5. What types of calibration blocks are used in ultrasonic inspection

6. Why couplant is required in ultrasonic inspection method?

Date:	Sign:	Grade:
-------	-------	--------

NON DESTRUCTIVE TEST

Experiment No:-11 Detection of flaws in materials through dye-penetrant test.

Tools & Instruments:

1. Cleaner Spray,
2. Penetrate Spray,
3. Developer Spray,
4. Welded Specimen,

Working principle:

The principle of liquid penetrate test is that is that liquids used enter small opening such as cracks by capillarity action. The rate and extent of this action are dependent upon which such a properties are surface tension, cohesion, adhesion and viscosity. They are also influenced by factors such as the condition of the surface of material.

For the liquid to penetrate effectively, the surface of the material must be thoroughly cleaned of all material that would obstruct the entrance of the liquid in to defect.

After cleaning the liquid penetrate is applied evenly over the surface and allowed to remain long enough to permit penetrate into possible discontinuous.

The liquid is then completely removed from the surface of the component and either a wet or a dry developer is applied. The liquid that has to applied the defect will then bleed out onto the surface and the developer will help delineated them.

Procedure:

Application:

Reference books:

3. Heat Treatment (Principles and Techniques) - By T.V. Rajan. CP. Sharma & Ashok Sharma, Prentice -Hall of India Pvt. Ltd., Tenth Printing (Revised Edition) December - 1999.
4. Introduction to Physical Metallurgy - By Sidney H. Avner. Mc-GRAW HILL International Edition, 14th Printing - 1988.

Date:	Sign:	Grade:
-------	-------	--------

